



Surface Mount

- **Low mounting profile, with maximum sensing ranges**
- **AC/DC supply (F42 Series)**
- **Configuration via pushbutton, or teach input**
- **Single or dual switch point outputs**
- **Analog voltage or current outputs**
- **Relay outputs**



Surface Mount

Sensing Ranges

F54: 35 mm ... 500 mm

F54: 60 mm ... 2 m

F42: 30 mm ... 500 mm

F42: 60 mm ... 2 m

F42: 200 mm ... 4 m

F42: 350 mm ... 6 m



Surface Mount

- **Monitoring presence/absence of conveyed bulk materials**
- **Traditional level control processes**
- **Sensing in dusty/dirty environments**

